

Under Review Notification

Raised By: Ketan Tailor

Product #: C250-C

Date: 19.09.09

Product Name: C250 CAGE ASSEMBLY

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank								Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Quarantine Tooling (Jigs, Fixtures, etc.)	Re-Work Stock	IPP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
C250-C	C250-C REV. C	Y	Y	N	N	Y	N	N	N	19-891	see below
C250-C-16	C250-C REV. C	Y	Y	N	N	Y	N	N	N	19-891	Modify grip length and cotter pin hole location

Description of Issue:

Grip length of Lifting Bolt is too short and threads are in contact with inner diameter of Cage Boss

Location of cotter pin hole is not dimensioned correctly, verify tolerance stack up with hardware and Cage Weldment

Distribution:	VP Operations	Director of Engineering	Customer Support Manager	Technical Support
	Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
	Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
	QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene